


FIRE RISK ASSESSMENT



Cuthbert Cooper Place (Block 16-46)

**Cuthbert Cooper Place (Block 16-46), Darnall,
Sheffield, South Yorkshire, S9 4JN**

| | |
|-----------------|-------------------------|
| VALID BETWEEN | 21/02/2023 - 21/02/2024 |
| ASSESSED BY | Brian Smith |
| ASSESSED ON | 21/02/2023 |
| APPROVED ON | 02/04/2023 |
| PROPERTY REF. | RB-HE7WR5 |
| ASSESSMENT REF. | RB-9U5NEE |
| VERSION | 1 |

1 INTRODUCTION

OVERVIEW

The Regulatory Reform (Fire Safety) Order 2005, which came into effect on 1st October 2006, applies to the majority of non-domestic premises. The legislation places certain obligations on the 'Responsible Person or Duty Holder' for the premises, that includes carrying out a suitable and sufficient fire risk assessment by a competent person. The assessment set out in this document is intended to satisfy this requirement. This assessment comes complete with a Certificate of Conformity to the BAFE SP205 Life Safety Fire Risk Assessment scheme.

ENFORCEMENT

Your local fire and rescue authority enforces this legislation. They have the power to inspect your premises to check that you are complying with your duties under the Order. They will look for evidence that you have carried out a suitable fire risk assessment and acted upon the significant findings of that assessment.

ASSESSMENT REVIEW

The fire risk in any building may be subject to change. Under the Order, part of the duties of the 'responsible person' is to review this assessment periodically and in the event of:

- A fire or near miss occurs
- Failure of fire safety systems (e.g. fire detection or emergency lighting)
- Changes to work processes undertaken in the building
- Alterations to the internal layout of the building
- Introduction, change of use or increase in the storage of hazardous substances
- Significant changes to the type and quantity and / or method of storage of combustible materials
- Significant changes in the number or type of people (e.g. young persons, those with disability)

MANAGING FIRE SAFETY

Good management of fire safety is essential to ensure that fires are unlikely to occur; that if they do occur they are likely to be controlled quickly, effectively and safely or that if a fire does occur and grow, to ensure that everyone in your premises are able to escape to a place of total safety easily and quickly.

SIGNIFICANT FINDINGS

The Significant Findings section contains actions that should be addressed based on their priority scores. Continue to implement control measures and monitor them for effectiveness.

What is a Fire Risk Assessment?

A fire risk assessment is an organised and methodical examination of your premises, the activities carried on there and the likelihood that a fire could start and cause harm.

Who is the Responsible Person?

The 'responsible person or duty holder' is typically the employer and any other person who may have control of any part of the premises, e.g. occupier, owner, or manager.

Assessment Risk Scoring & Methodology

The building risk score is a subjective calculation based on how likely the assessor believes a fire is to occur and how severe the consequences (severity of injury or death) might be if that fire were to happen.

| SEVERITY ▾ LIKELIHOOD ▾ | SLIGHT HARM | MODERATE HARM | EXTREME HARM |
|----------------------------|-------------|---------------|--------------|
| LOW | TRIVIAL | TOLERABLE | MODERATE |
| MEDIUM | TOLERABLE | MODERATE | SUBSTANTIAL |
| HIGH | MODERATE | SUBSTANTIAL | INTOLERABLE |

| | | |
|----------------------|------------|---|
| SLIGHT HARM | SEVERITY | Outbreaks of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs). Typically high level of compartmentation. |
| MODERATE HARM | SEVERITY | Reasonable risk of fire spread involving multiple occupants which could result in significant injury. Eg, poor construction detailing or breaches to purpose built construction. |
| EXTREME HARM | SEVERITY | Significant potential for serious injury or death of one or more occupants. Includes high dependency occupants such as a care home or properties with poor compartmentation. |
| LOW | LIKELIHOOD | Very low likelihood of fire as a result of negligible potential sources of ignition. |
| MEDIUM | LIKELIHOOD | Normal fire hazards for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings). |
| HIGH | LIKELIHOOD | Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire. |
| TRIVIAL | RATING | Limited action is required, review FRA as recommended; existing controls are generally satisfactory. |
| TOLERABLE | RATING | No major additional controls required. However, there might be a need for some improvements. |
| MODERATE | RATING | Essential action must be made to reduce the risk. Risk reduction measures should be implemented within a defined time period. |
| SUBSTANTIAL | RATING | Considerable resources might have to be allocated to reduce the risk. Improvements should be undertaken urgently. |
| INTOLERABLE | RATING | Imminent risk of significant harm. Immediate action required. |

Action Priorities

Separately from the building's risk score, every action is given a priority. Priorities are defined based on how easily an action can be completed and how much it should reduce the risk.

| D | C | B | A |
|--|--|---|---|
| These actions should be implemented when the opportunity arises (such as the refurbishment of a building), but ideally within 2 years. | These actions may be more complicated or require a greater degree of planning. They should be completed within 6 months. | These actions should be implemented with a reasonable degree of urgency but at least within 3 months. | These actions should be implemented as soon as possible. Where they cannot be affected immediately, interim measures may be required to ensure occupant safety. |

CERTIFICATE OF CONFORMITY

LIFE SAFETY FIRE RISK ASSESSMENT



The life safety elements of this fire risk assessment comply with the BAFE SP205 scheme which ensures that we and our risk assessment staff have met the required technical and quality management standards.

Oakleaf Surveying Ltd (BAFE 301310) certify all requirements in the BAFE SP205 scheme in respect of life safety fire risk assessment have been complied with. Any questions can be addressed to the assessor or the quality manager.

ASSESSMENT AND CERTIFICATE REFERENCE
RB-9U5NEE

PRODUCED FOR THE RESPONSIBLE PERSON
Oakleaf Surveying Ltd

ASSESSED ON, BY
21/02/2023, Brian Smith

SPECIFICATION CONFORMS TO
ISO 9001 Quality Management System

FIRE QC ON, BY
30/03/2023, Andy Whiting

ASSESSMENT SCOPE
Cuthbert Cooper Place Block 16 to 46.

APPROVED / VALIDATED ON
02/04/2023

ASSESSMENT SCOPE CHANGE
None.

START DATE — RECOMMENDED REVIEW DATE
21/02/2023 — 21/02/2024

SIGNIFICANT FINDINGS
8 Actions / 28 Controls

Assessed Property

PROPERTY NAME
Cuthbert Cooper Place (Block 16-46)

ADDRESS
Cuthbert Cooper Place (Block 16-46)
Darnall
Sheffield
South Yorkshire
S9 4JN

PROPERTY REFERENCE
RB-HE7WR5

FIRE RISK RATING

LIKELIHOOD **LOW**

Very low likelihood of fire as a result of negligible potential sources of ignition.

SEVERITY **MODERATE HARM**

Reasonable risk of fire spread involving multiple occupants which could result in significant injury. Eg, poor construction detailing or breaches to purpose built construction.

RISK **TOLERABLE**

No major additional controls required. However, there might be a need for some improvements.

ASSESSING / ACCREDITED ORGANISATION

Oakleaf Surveying Ltd
McGowan House, 10 Waterside Way, The Lakes, Northampton, NN4 7XD
01604 643100 — www.theoakleafgroup.co.uk



THIRD PARTY CERTIFICATION BODY

NSI, Sentinel House, 5 Reform Road, Maidenhead, SL6 8BY

Assessor Remarks

The risk is identified as Tolerable on the basis that there are high standards of housekeeping on site. Limited action is required, review the Fire Risk Assessment as recommended and address the actions have been raised.

3 PROPERTY

Address

PROPERTY NAME

Cuthbert Cooper Place (Block 16-46)

PROPERTY REFERENCE

RB-HE7WR5

OCCUPANT TYPES

Residents, Staff, Visitors

ADDRESS

Cuthbert Cooper Place (Block 16-46)

Darnall

Sheffield

South Yorkshire

S9 4JN

Premises Summary

Premises Summary

Description

Property 16-46 Cuthbert Cooper Place is a block of 30 flats over 4 floors. The block is managed by Moreland Estates Ltd along with Arches Housing having 1 flat within the block (Flat 26). As such, Arches Housing has no direct control over the communal areas but does communicate with the managing agent as required. There is a single stairwell with each floor being lobbied and a ground floor exit door. The building is located in a residential area, is brick built with a flat roof, construction not confirmed. There is a car park to the front with a Bin Room (no longer in use) located adjacent to the block entrance door. Neighbouring premises do not represent a significant hazard.

Arches Housing are NOT the Landlord of this block, they are the tenant owners of one flat which is sub-let.

Use of Premises

Residential general let.

Construction

Steel Frame brick and masonry concrete floors. The basic construction of the building is that of load bearing blockwork external walls with internal block load bearing partition walls forming compartmentation between the apartments. All the internal walls are dry-lined in plasterboard. The structural floor construction is that a concrete beam and block type with a floating chipboard deck above and plasterboard ceilings below (supported off battens to the soffit of the structural floor). The roof gives the visual appearance is that of a upper flats compartmentation continues throughout.

Number of Floors

4.

Number of Occupants

60 based on 2 people per flat.

People Especially at Risk

None reported.

Stairways

1.

Final Exits

1.

Evacuation Procedure

Stay Put from within the flats with Simultaneous Evacuation from occupied communal areas.

Recent Fire History

None reported.

Additional Facilities

None.

Responsible Person
Moreland Estates Ltd.

Competent Person
Nichola Maguire for Arches Housing.

Guidance Used
Fire Safety in Purpose-Built Blocks of Flats

4 SIGNIFICANT FINDINGS

This assessment identifies 8 actions and 28 controls.

| 8 ACTIONS | INCOMPLETE | 28 CONTROLS | ONGOING |
|-----------|------------|-------------|---------|
| A | 2 | ALL | 28 |
| B | 6 | | |

Sources of Ignition

The assessor has reviewed the potential sources of ignition in and around the premises. This includes electrical ignition sources, smoking, arson and lightning protection.

? Are electrical ignition sources, such as fixed wiring & PAT, being adequately maintained and tested?

NO

There is no evidence that the fixed electrical installation has been periodically inspected and tested.

B

Arrange for the fixed electrical installation to be tested and inspected in accordance with BS 7671.

REFERENCE RB-BS348J
DUE 02/05/2023
CATEGORY Maintenance: Electrical

WHY Fixed wire testing checks the condition of the electrics against the UK standard for the safety of electrical installations, BS 7671. Each circuit's cable and accessories is inspected for visual damage and wear and tear, followed by a series of tests to verify the wiring is safe and the circuit is wired correctly.

Fixed wire testing is a legal requirement for any organisation to ensure compliance with legal requirements to ensure the building's electrical system is safe, maintained and tested by competent, qualified individuals. In doing so you are ensuring the provision of a safe and hazard-free environment for employees, visitors and the public at large.

Electrical installations deteriorate with age and use. Regular testing and inspections will identify potential or existing electrical faults or hazards to be remedied.

Fixed wire testing is also usually mandatory for insurance purposes.

Fixed wire testing should be performed by competent persons – generally this would mean a qualified electrical engineer.

Following the electrical testing and inspection, you will be issued an Electrical Condition Report (EICR) for the fixed wire test.

A satisfactory EICR issued by a competent and qualified individual confirms compliance with the Health and Safety at Work Act 1974 and the Electricity at Work Regulations 1989.

LOCATION Arches Housing is to put Enquiries to Landlord via email or recorded mail to provided satisfactory information.

There are no portable appliances provided to the block of flats that fall under the responsibility of the client.

? Does basic security against arson by outsiders appear reasonable?

YES

There is secure access to the premises, available to authorised persons only. During the inspection, there did not appear to be significant fire loads which may be ignited by others and which would pose a significant fire risk to the building occupants.

WHY To reduce the likelihood of deliberate ignition inside, or within close proximity to openings in, the building.



? Are reasonable measures taken to prevent fires as a result of smoking? **YES**

● No smoking is permitted within the building, or within close proximity of the building, as part of the organisations smoking policy.

WHY Smoke-free legislation was introduced in England in 2007, banning smoking in nearly all enclosed workplaces and public spaces.

The enforcement is for public health but also mitigates and reduces the risk of accidental ignition and fires within all buildings.



? Are external waste bins stored in a suitable location? **YES**

● External waste bins are stored away from the premises, behind fencing.

WHY This reduces the likelihood of arson attacks, limits potential fire growth and reduces the likelihood of external fires entering the building through its openings.



? Is lightning protection fitted to the building? **NO**

● No lightning protection is required for a building of this height.

Means of Escape

The proper provision of means of escape is an essential part of fire safety measures in any and all premises. We have reviewed whether adequate escape routes are provided, whether they can be easily used and navigated, and whether the provision of emergency lighting, or other means of lighting, are sufficient. Statements in the report regarding escape lighting are based on visual inspection only. The mains services were live at the time of inspection. No test of luminance levels was carried out.

? Are the means of escape adequate? **YES**

● Single stairway means of escape is acceptable.


LOCATION Throughout the premises.

? Is there suitable emergency lighting provided to illuminate the means of escape? **YES**

● An emergency light fitting within the corridor had appeared to of burnt out, the unit has been half dissembled, there is other emergency lighting on the corridor.

Arrange with the landlord to change the fitting and reinstate the emergency light.

WHY To illuminate the escape route if the property loses electrical power.




● Emergency lighting is provided throughout the means of escape internally.

WHY To illuminate the escape route if the property loses electrical power.

A

REFERENCE RB-1NMJRE
DUE 02/05/2023
CATEGORY Maintenance:
Emergency Lighting

LOCATION Throughout the premises.



? Are suitable maintenance records available?

A visual inspection was undertaken and no test of the illuminance levels or verification of full compliance with the relevant British Standard has been carried out. No evidence was available at the time of the assessment to show that the emergency lighting system is subject to regular maintenance.

Management must ensure that the emergency lighting system is maintained appropriately and records are kept, in accordance with BS 5266.

WHY Records were either not made available, or within the recommended testing frequency and, or, identified faults or remedial actions being required.

NO

B

REFERENCE RB-PH1FPT
DUE 02/06/2023
CATEGORY Maintenance:
Emergency Lighting

? Are the travel distances reasonable?

The maximum travel distances on all floors are within the accepted limits for this type of occupancy.

WHY To ensure occupants can reach a place of safety in the shortest travel time.

LOCATION Throughout premises.

YES

? Are all doors on escape routes easily opened?

All final exit doors are provided with a single method of opening.

WHY To enable easy and immediate egress.



YES

? Is adequate fire exit and other fire safety related signage provided?

A fire action notice, detailing the evacuation procedure, is in place in the common areas, along with directional signage.

WHY To provide information to all occupants of what to do in the event of fire within the building.

LOCATION Throughout premises.




YES

? Are the directional signs correct?

The provision of fire exit signage is sufficient to aid personnel to a place of relative safety leading to ultimate safety and fresh air.

WHY To indicate to occupants that are unfamiliar to the property the final exit from the building to a place of relative safety

LOCATION Throughout premises.




YES

? Is smoke ventilation provided?

An Automatic Opening Vent (AOV) is provided in the protected stairway, activated by a smoke detection head.

YES

WHY The primary objective of the smoke ventilation system is to protect the staircase and protect the common circulation areas.



? Is the smoke ventilation system being regularly serviced?

- No evidence was available to confirm that the mechanical smoke ventilation system is being regularly maintained.

Arrange for a contractor to undertake testing and maintenance.

It is recommended that smoke control equipment is serviced twice a year by a specialist smoke control contractor and maintenance certificates should be produced and kept in a maintenance log.

WHY Smoke ventilation saves lives and it is absolutely essential that the system is maintained and serviced on a regular basis to ensure that it works correctly when activated during a fire.

NO


B

REFERENCE RB-6J5N8V
DUE 02/07/2023
CATEGORY Maintenance: Fire Alarms

? Are the means of escape clear of combustible items and obstructions, and is the standard of housekeeping acceptable?

- The means of escape were free of combustible items at the time of the assessment.

WHY All emergency routes and exits must lead as directly as possible to a place of safety and be adequate for everyone to escape quickly and safely. It is essential that escape routes, and the means provided can be used safely, are managed and maintained to ensure that they remain usable and available at all times when the premises are occupied. Corridors and stairways that form part of escape routes should be kept clear and hazard free at all times. Items that may be a source of fuel or pose an ignition risk should not normally be located on any corridor or stairway that will be used as an escape route.



YES

Fire Doors and Compartmentation

The provision of passive fire protection, in the form of fire resisting walls, ceilings and doors play an important part in the fire safety provisions in the building. The extent to which they are required has been assessed, and we have reviewed the provision of fire resisting doors, fire resisting walls, and the separation of roof voids, where possible. Statements regarding the fire resistance of the structure have been based on typical expected resistances of materials and construction. They comprise a visual inspection of the readily accessible areas only.

? Are flat entrance doors and doors to the common parts of a suitable fire resisting standard?

- The fire door to the stairway was not closing fully onto its rebates.

Arrange for the landlord to adjust the door to ensure it closes fully.

WHY Maintain integrity of compartmentation and prevent fire spread.



- Fire doors to the common parts are of a suitable fire resisting standard.

YES

A

REFERENCE RB-CT419T
DUE 02/05/2023
CATEGORY Building: Doors



? Is the compartmentation of the common areas and means of escape adequate? **YES**

- Floors and walls appeared to be in good condition, with no apparent openings or breaches that would permit the uncontrolled spread of fire and smoke.

LOCATION Throughout premises.




? Are roof voids adequately compartmented? **NO HATCH WITHIN THE COMMON AREAS.**

- There is no loft hatch within the common parts.

? Are wall and ceiling linings appropriate to limit fire spread? **YES**

- Wall surfaces for the most part appear to be of an appropriate standard and that is to EN 13501.

LOCATION Throughout premises.




? Does the exterior of the building adequately resist the spread of fire? **YES**

- The exterior of the building is of brick construction and would not promote external flame spread.

WHY To reduce the risk of fire and smoke spread.

LOCATION Throughout premises.



Means of Giving Warning

We have reviewed the provision of a fire detection and alarm system in the building, and its suitability in line with the evacuation procedure, and other fire safety systems. For domestic premises we have where possible reviewed whether domestic smoke alarms have been provided in the individual flats. Statements regarding the fire alarm system are based on visual inspection only; no audibility tests have been carried out.


? Is a suitable fire detection and alarm system in place? **YES**

- An Automatic Opening Vent (AOV) operated by a smoke detector is provided within the stairwells.

LOCATION Within the stairwells.



- Fire detection and alarm system provided throughout, comprising smoke detection and alarm call points.



? Are there records for the fire alarm system?

- No records of maintenance or testing were available at the time of the survey. If not suitably maintained, ensure that the fire alarm installation is suitably maintained and tested as soon as possible by a 3rd party accredited contractor. Recommend Arches Housing contact the Landlord by email or recorded letter to obtain confirmation of Alarm testing and maintenance

WHY To ensure that the installation has not deteriorated and is functional. RRO Maintenance and testing Article 17 refers.
 LOCATION Throughout premises.

NO

B

REFERENCE RB-VZSRQF
 DUE 02/07/2023
 CATEGORY Procedures: Log Books

Firefighting Arrangements

With regards to the height, complexity and use of the building we have made an assessment of the firefighting arrangements. This includes the provision of fire extinguishers, fire brigade access, and the provision of sprinklers.

? Is a sprinkler system provided?

NOT REQUIRED

- A sprinkler system is not currently required for a building under 11 metres in height.

? Is a firefighting shaft provided?

NOT REQUIRED

? Where required are the correct fire extinguishers provided, and are they suitably positioned?

NOT REQUIRED

- Fire extinguishers are not provided or required in the common areas.


WHY Not recommend for use by untrained tenants, action plan should be leave premises and attend assembly point, closing the fire doors.

? Is adequate fire brigade access available to the building?

YES

- Suitable Fire Brigade access is available to the front of the property, from the street.


WHY To support the Fire Service when attending the property to position fire appliances as close to the building as reasonably practical.



? Are there suitable floor numbers/wayfinding signage at each level?

NO

- Floor numbering not required on this building due to the simple layout of 3 floors and protected staircase. Directional signage has been installed within the premises.



Management and Housekeeping

As part of the fire risk assessment, fire safety management needs to be regarded as of equal importance to fire protection measures. In its broadest sense, fire safety management includes certain policies and procedures designed to prevent the occurrence of fire by eliminating or controlling fire hazards. We have assessed the standard of housekeeping in the building, the evacuation procedure that is in place, the presence of staff, and any occupants that have been deemed to be especially at risk.

As of the 23 January 2023: The Fire Safety (England) Regulations 2022 will become a legal requirement in all multi-occupied residential buildings in England. The regulations will require Responsible Persons to provide residents of all multi-occupied residential buildings with two or more sets of domestic premises (that have common parts) information on the importance of fire doors to a building's fire safety. Regulation 10 of The Fire Safety (England) Regulations 2022 requires that residents are given information that:


- Fire doors should be kept shut when not in use.
- Residents or their guests should not tamper with self-closing devices.
- Residents should report any fault or damage immediately to the Responsible Person.

Additionally, the above information must be provided by the Responsible Person to any new resident as soon as reasonably practicable after the resident moves into their flat. The Responsible Person must also remind all residents about this information at periods not exceeding 12 months starting from when the regulations come into force.




Where a resident wants to alter or change their front door, this should be done with the knowledge and agreement of the Responsible Person to ensure that it does not negatively impact upon the overarching fire risk assessment for the premises.

| | |
|---|--|
| <p>? Is the evacuation procedure suitable, and supported by the provisions on site?</p> <p>YES</p> <p>● A mixed policy is in place of simultaneous evacuation upon hearing the alarm within the common areas and this is supported by automatic fire detection and alarm system throughout.</p> <p>The flats have a stay-put policy supported by adequate compartmentation, unless affected by fire or smoke.</p> <p><small>LOCATION</small> Throughout premises.</p> | |
| <p>? Are suitable records held relating to maintenance and management?</p> <p>NO</p> <p>● It was not confirmed that the fire detection and alarm system is being tested and maintained. Confirm that testing is being completed in line with BS 5839.</p> <p><small>WHY</small> Statutory requirement Maintenance and testing Article 17 RRO 2004.</p> <p><small>LOCATION</small> Arches Housing is to put enquiries to the Landlord via email or recorded mail to provide satisfactory information.</p> | <p>B</p> <p><small>REFERENCE</small> RB-9ZR669</p> <p><small>DUE</small> 02/07/2023</p> <p><small>CATEGORY</small> Maintenance: Fire Alarms</p> |
| <p>? Are staff located at the premises?</p> <p>NO</p> <p>● No staff are based on the site.</p> | |
| <p>? Is there a designated responsible person and safety assistant for fire safety management in the premises?</p> <p>NO</p> <p>● Request landlord (Moreland Estates Ltd.) to provide information on the responsible person.</p> <p><small>WHY</small> Statutory requirement RRO Article 8.</p> <p><small>LOCATION</small> Arches Housing is to put enquiries to the Landlord via email or recorded mail to provide satisfactory information.</p> | <p>B</p> <p><small>REFERENCE</small> RB-57ASQ2</p> <p><small>DUE</small> 02/07/2023</p> <p><small>CATEGORY</small> Procedures: Fire Drills</p> |
| <p>? Have any occupants been identified that may be deemed to be especially at risk?</p> <p>NO</p> <p>● The assessor was not aware of any occupants that may be especially at risk at the time of the assessment.</p> <p><small>LOCATION</small> Throughout premises.</p> | |
| <p>? Were all relevant areas of the building accessed as part of the assessment?</p> <p>YES</p> <p>● The risk assessor accessed all areas of the property.</p> <p><small>LOCATION</small> Throughout premises.</p> | |


5 PHOTOS



Photos Continued...



Photos Continued...



Photos Continued...





Rely on us on for clear and practical advice. Small enough to respond and care, big enough to deliver consistency and quality every time.

We believe strongly in third party approval, that's why our consultants hold professional accreditations from the IFE and IFSM and the business itself is accredited by UKAS and NSI.

RISK ASSESSMENT • STRATEGY • CONSULTANCY • ENGINEERING • COMPARTMENTATION

ADDRESS
Oakleaf Surveying Ltd
McGowan House
10 Waterside Way
The Lakes
Northampton
NN4 7XD

TELEPHONE
01604 643100
EMAIL
info@theoakleafgroup.co.uk
WEBSITE
www.theoakleafgroup.co.uk

