DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT Requirements For Electrical Installations - BS 7671 IET Wiring Regulations Report Reference: 3799

1_DETAI	LS OF T	HE PERS	ON ORDERIN	IG TH	E REPORT						
Client: Arches Housing Ltd											
Address:	Address: 122 Burngreave Road, Sheffield, S3 9DE										
2 REAS	ON FOR I	PRODUC	ING THI S REI	PORT							
Reason for			51								
To assess compliance with BS 7671.											
Date(s) on w	Date(s) on which inspection and testing was carried out: 28/03/2022										
3 DETAI	LS OF T	HE INST.	ALLATION W	нісн	IS THE SUBJ	ECT	OF THIS REPORT				
Installation	Address:	Installatio	n Address, Land	ord Su	ipply 418 Abbeyd	lale F	Road, Sheffield				
Estimated ag	e of wiring	system:	>20 years		Evidence of additio alterations:	ons/	N/A if yes, estimated age:	N/A	years		
Installation re	ecords avail	able? (Regu	llation 651.1)	N/A			Date of last inspection:	N/A			
	4 EXTENT AND LIMITATIONS OF INSPECTION AND TESTING Extent of the electrical installation covered by this report:										
-	Agreed limitations including the reasons (see Regulation 653.2): 25% of the installation in accordance with item 3.8.2 of Guidance Note 3.										
Agreed with:		Arches H	lousing Ltd								
Operational limitations including the reasons: -											
The inspection and testing detailed in this report and accompanying schedules have been carried out in accordance with BS 7671:2018 (IET Wiring Regulations) as amended to 2020. It should be noted that cables concealed within trunking and conduits, under floors, in roof spaces, and generally within the fabric of the building or underground, have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.											
					NSTALLATION						
See page 3 for a summary of the general condition of the installation in terms of electrical safety.         Overall assessment of the installation in terms of it's suitability for continued use*:         * An unsatisfactory assessment indicates that dangerous (Code C1) and/or potentially dangerous (Code C2) conditions have been identified.											
6       RECOMMENDATIONS         Where the overall assessment of the suitability of the installation for continued use on page 1 is stated as 'UNSATISFACTORY',         I/We recommend that any observations classified as 'Code 1 - Danger Present' or 'Code 2 - Potentially dangerous' are acted upon as a matter of urgency.         Investigation without delay is recommended for observations identified as 'FI - Further Investigation Required'.         Observations classified as 'Code 3 - Improvement recommended' should be given due consideration.         Subject to the necessary remedial action being taken, I/we recommend that the installation is further inspected and tested by:         Note: The proposed date for the next inspection should take into consideration the frequency and quality of maintenance that the											
	-						requency and quality of maintena d should be agreed between relev				

7 <u>OB</u>	7 OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKEN								
Referring to the attached schedules of inspection and test results, and subject to the limitations specified on page 1									
of this report under 'Extent of the Installation and Limitations of Inspection and Testing': There are no items adversely affecting electrical safety									
		or							
N/A T	ne following observations and recommendations	are made							
Item No		Observations	Classification Code						
One of the following codes, as appropriate, has been allocated to each of the observations made above to indicate to the person(s responsible for the installation the degree of urgency for remedial action.          C1       Danger Present       C2       Potentially dangerous       C3       Improvement       FI       Further investigation         Risk of injury. Immediate       required       required       C3       Improvement       FI       Further investigation									
	Immediate remedial action required for items: N/A								
Urgent remedial action required for items: N/A									
Improvement recommended for items: N/A									
	investigation required for items:								
untilei	investigation required for items.	N/A							

This form is based on the model shown in Appendix 6 of BS 7671:2018.

General condition of the installation (in terms of electrical safety):

## Good

## 9 DECLARATION

I/We, being the signatures below inspection and te provides an accu in section 4 of the Trading Title:	<ul> <li>, particulars</li> <li>, particulars</li> <li>, hereby</li> <li>, have</li> <li>, hereby</li> </ul>	of whic y declare nent of t	h are e that he coi	descri the in nditior	bed abo formation of the e	ve, havir on in this	ng exerc report,	ised rea includir	asonal ng the	ble skill observa	and care ations an	when carrying d the attached	out the schedu	les,
Address:	28 Salisbury Avenue Dronfield								Registration Number (if applicable):			16147		
	Dioinicia							Те	lepho	ne Numi	ber:	07833 6083	363	
				F	Postcode	: S18	1WD							
For the INSPEC	CTION, TEST	ING AN	ID AS	SESS	MENT o	f the re	port:							
Name: Mi	ichael Shiple	уy	Posit	tion:	El	ectriciar	ı	Signat	ure:		MShiph	Date:	28/03/	/2022
Report reviewe		orised f	or iss	sue by							$ \rightarrow $			
Name:	Tim Turner		Posit	tion:	El	ectriciar	۱	Signat	ure:			Zar Date:	28/03/	/2022
10 TEST IN: Details of Test			+ o + o - o	antal a	und (on oo		h a na ) .							
Multi-functional:	mstruments		9043		10/01 85		arth elec	trode r	esista	nce:		904306	3	
Insulation resista	ance:		9043	063		Ea	arth faul	t loop iı	loop impedance:			9043063		
Continuity:			9043	063		R	CD:		·			904306	3	
11 SUPPLY	CHARACT	ERIS	TICS	S ANE	D EAR	THING	ARRA		MEN	TS	_			
Earthing Arrangements		per and <sup>-</sup>	Туре с	of Live		1	Nature of				1	Supply Prote	ective De	evice
	1-phase	Condu			N/A	Nomin	U:	240	νu	lo: 23		BS(EN):	LIM	
1	(2 wire): 3-phase			vire): hase	N/A	¦ voltage						Гуре:	-	
	(3 wire):	I/A		wire):	IN/A		Nomina Prospec		-	. 50	112		100	) A
TT N/A	Other:		N//	4 			current,		art -	2.4	KA I	Rated current: Short-circuit	100	
	Confirmation	of supp	oly pol	larity:	•	, , , ,	Externa loop im			0.1	Ω	capacity:	-	kA
12 PARTICU	JLARS OF	INST	ALL	ΑΤΙΟ	N REF	ERREI	Ο ΤΟ Ι	N TH	e re	PORT				
Means of Earthi Distributor's				C			tion Eart	th Electi	rode (	where a	oplicable			
facility: Installation	~	Type: Resista	ance		N/A	L .	Locatio Metho					N/A		
earth electrode:	N/A	to Earl			/Α Ω		measu	irement	t:			N/A		
Maximum Demai	nd (Load):	- Ar	nps		otective gainst ele		• •		A	DS				
Main Switch / Sw Type	vitch-Fuse / C	ircuit-B	reaker				Supply	 /				nain switch:		
BS(EN): 6094	7-3 Isolator		ent ra	5		A 00	conduc		Со	oper	Rated re	esidual ng current (l∆n	): -	mA
Number of poles: 2			e/devidevide	ce rati :	ng 1	A 00	Supply			2	Rated ti	me delay:	N/	/A ms
			age ra		2	40 V	conduo csa:	ctors	25	mm <sup>2</sup>	Measure time (at	ed operating	-	· ms
Earthing and Pro	tective Bondi	ng Cond	uctors				Bo				conducti	ve parts		
Earthing conduct Conductor		65.21	14		001110001011		o water pes:	ater installation Ns:		N/A	To gas install pipes:	ation	N/A	
material:				vermeu.			To oil installation		on	N/A	To lightning protection:		N/A	
Main protective bonding conductors Conductor material Copper csa: 10 mm <sup>2</sup>					Connection/ pipes continuity To st			tructural		N1/A	To other serv			
material:	Copper	csa:	10 1	mm–	verified:	-	st	eel:			N/A	IN	/A	

3 11	ISPECTION SCHEDULE FOR DOMESTIC & SIMILAR PRE	MISES WITH UP TO 100A S	UPPLY
Item	Description	Comments	Outcome
1.0	EXTERNAL CONDITION OF INTAKE EQUIPMENT (VISUAL INSPECTI	ON ONLY)	
1.1	Service cable	-	~
1.2	Service head	-	~
1.3	Earthing arrangement	-	~
1.4	Meter tails	-	~
1.5	Metering equipment	-	~
1.6	Isolator (where present)	-	~
2.0	PRESENCE OF ADEQUATE ARRANGEMENTS FOR OTHER SOURCES SUCH AS MICROGENERATORS (551.6; 551.7)	-	N/A
3.0	EARTHING / BONDING ARRANGEMENTS (411.3; Chap 54)		
3.1	Presence and condition of distributor's earthing arrangement (542.1.2.1; 542.1.2.2)	-	~
3.2	Presence and condition of earth electrode connection where applicable (542.1.2.3)	-	N/A
3.3	Provision of earthing/bonding labels at all appropriate locations (514.13.1)	-	~
3.4	Confirmation of earthing conductor size (542.3; 543.1.1)	-	N/A
3.5	Accessibility and condition of earthing conductor at MET (543.3.2)	-	N/A
3.6	Confirmation of main protective bonding conductor sizes (544.1)	-	N/A
3.7	Condition and accessibility of main protective bonding conductor connections (543.3.2; 544.1.2)	-	~
3.8	Accessibility and condition of other protective bonding connections (543.3.1; 543.3.2)	-	~
4.0	CONSUMER UNIT(S) / DISTRIBUTION BOARD(S)		
4.1	Adequacy of working space/accessibility to consumer unit/distribution board (132.12; 513.1)	-	~
4.2	Security of fixing (134.1.1)	-	~
4.3	Condition of enclosure(s) in terms of IP rating etc (416.2)	-	~
4.4	Condition of enclosure(s) in terms of fire rating etc (421.1.201; 526.5)	-	~
4.5	Enclosure not damaged/deteriorated so as to impair safety (651.2)	-	~
4.6	Presence of main linked switch (as required by 462.1.201)	-	~
4.7	Operation of main switch (functional check) (643.10)	-	~
4.8	Manual operation of circuit-breakers and RCDs to prove disconnection (643.10)	-	~
4.9	Correct identification of circuit details and protective devices (514.8.1; 514.9.1)	-	~
4.10	Presence of RCD six-monthly test notice at or near consumer unit/distribution board (514.12.2)	-	~
4.11	Presence of non-standard (mixed) cable colour warning notice at or near consumer unit/distribution board (514.14)	-	~
4.12	Presence of alternative supply warning notice at or near consumer unit/distribution board (514.15)	-	N/A
4.13	Presence of other required labelling (please specify) (Section 514)	-	~
4.14	Compatibility of protective devices, bases and other components; correct type and rating (No signs of unacceptable thermal damage, arcing or overheating) (411.3.2; 411.4; 411.5; 411.6; Sections 432, 433)	-	~
UTCON ccepta conditio	ble Unacceptable Improvement C2 Further	verified N/V Limitation LIM appli	ot cable N. Page: 4 c

Item	Description	Compared to the second se	0
	Description	Comments	Outcom
4.15	Single-pole switching or protective devices in line conductor only (132.14.1; 530.3.3)	-	~
4.16	Protection against mechanical damage where cables enter consumer unit/distribution board (132.14.1; 522.8.1; 522.8.5; 522.8.11)	-	~
4.17	Protection against electromagnetic effects where cables enter consumer unit/distribution board/enclosures (521.5.1)	-	~
4.18	RCD(s) provided for fault protection - includes RCBOs (411.4.204; 411.5.2; 531.2)	-	~
4.19	RCD(s) provided for additional protection/requirements - includes RCBOs (411.3.3; 415.1)	-	~
4.20	Confirmation of indication that SPD is functional (651.4)	-	N/A
4.21	Confirmation that ALL conductor connections, including connections to busbars, are correctly located in terminals and are tight and secure (526.1)	-	~
4.22	Adequate arrangements where a generating set operates as a switched alternative to the public supply (551.6)	-	N/A
4.23	Adequate arrangements where a generating set operates in parallel with the public supply (551.7)	-	N/A
5.0	FINAL CIRCUITS		
5.1	Identification of conductors (514.3.1)	-	LIM
5.2	Cables correctly supported throughout their run (521.10.202; 522.8.5)	-	LIM
5.3	Condition of insulation of live parts (416.1)	-	~
5.4	Non-sheathed cables protected by enclosure in conduit, ducting or trunking (521.10.1)	-	~
5.4.1	To include the integrity of conduit and trunking systems (metallic and plastic)	-	~
5.5	Adequacy of cables for current-carrying capacity with regard for the type and nature of installation (Section 523)	-	~
5.6	Coordination between conductors and overload protective devices (433.1; 533.2.1)	-	~
5.7	Adequacy of protective devices: type and rated current for fault protection (411.3)	-	~
5.8	Presence and adequacy of circuit protective conductors (411.3.1; Section 543)	-	~
5.9	Wiring system(s) appropriate for the type and nature of the installation and external influences (Section 522)	-	~
5.10	Concealed cables installed in prescribed zones (see Section 4. Extent and Limitations) (522.6.202)	-	LIM
5.11	Cables concealed under floors, above ceilings or in walls/partitions, adequately protected against damage (see Section 4. Extent and Limitations) (522.6.204)	-	LIM
5.12	Provision of additional requirements for protection by RCD not exc	eeding 30mA:	
5.12.1	For all socket-outlets of rating 32A or less, unless an exception is permitted (411.3.3)	-	N/A
5.12.2	For the supply of mobile equipment not exceeding 32A rating for use outdoors (411.3.3)	-	N/A
5.12.3	For cables concealed in walls at a depth of less than 50mm (522.6.202; 522.6.203)	-	N/A
5.12.4	For cables concealed in walls/partitions containing metal parts regardless of depth (522.6.203)	-	N/A
5.12.5	Final circuits supplying luminaires within domestic (household) premises (411.3.4)	-	N/A
UTCON	IES		
Acceptal		N/V/ Limitation / LIM	lot icable

15 IN	SPECTION SCHEDULE FOR DOMESTIC & SIMILAR PRE	MISES WITH UP TO 100A S	UPPLY						
Item	Description	Comments	Outcome						
5.13	Provision of fire barriers, sealing arrangements and protection against thermal effects (Section 527)	-	~						
5.14	Band II cables segregated/separated from Band I cables (528.1)	-	~						
5.15	Cables segregated/separated from communications cabling (528.2)	-	~						
5.16	Cables segregated/separated from non-electrical services (528.3)	-	~						
5.17	Termination of cables at enclosures - indicate extent of sampling in Section 4 of the report (Section 526)								
5.17.1	Connections soundly made and under no undue strain (526.6)	-	~						
5.17.2	No basic insulation of a conductor visible outside enclosure (526.8)	-	~						
5.17.3	Connections of live conductors adequately enclosed (526.5)	-	~						
5.17.4	Adequately connected at point of entry to enclosure (glands, bushes etc.) (522.8.5)	-	~						
5.18	Condition of accessories including socket-outlets, switches and joint boxes ( $651.2(v)$ )	-	~						
5.19	Suitability of accessories for external influences (512.2)	-	~						
5.20	Adequacy of working space/accessibility to equipment (132.12; 513.1)	-	~						
5.21	Single-pole switching or protective devices in line conductors only (132.14.1, 530.3.3)	-	~						
6.0	LOCATION(S) CONTAINING A BATH OR SHOWER								
6.1	Additional protection for all low voltage (LV) circuits by RCD not exceeding 30mA (701.411.3.3)	-	N/A						
6.2	Where used as a protective measure, requirements for SELV or PELV met $(701.414.4.5)$	-	N/A						
6.3	Shaver sockets comply with BS EN 61558-2-5 formerly BS 3535 (701.512.3)	-	N/A						
6.4	Presence of supplementary bonding conductors, unless not required by BS 7671:2018 (701.415.2)	-	N/A						
6.5	Low voltage (e.g. 230 volt) socket-outlets sited at least 3m from zone 1 (701.512.3)	-	N/A						
6.6	Suitability of equipment for external influences for installed location in terms of IP rating (701.512.2)	-	N/A						
6.7	Suitability of accessories and controlgear etc. for a particular zone (701.512.3)	-	N/A						
6.8	Suitability of current-using equipment for particular position within the location (701.55)	-	N/A						
7.0	OTHER PART 7 SPECIAL INSTALLATIONS OR LOCATIONS List all other special installation or locations present, if any. (Record separ	ately the results of particular inspection	ons)						
7.1		-	~						
7.2		-	~						
7.3		-	~						
7.4		-	~						
7.5		-	~						
7.6		-	~						
7.7		-	~						
7.8		-	~						
7.9		-	~						
7.10		-	~						
OUTCOMES									
Acceptat conditio			ot cable						

## 16 SCHEDULE OF CIRCUIT DETAILS AND TEST RESULTS Designation of Prospective fault D.B. 1 Stairs cupboard Location: 2.4 kΑ consumer unit: current: Circuit Circuit conductors: BS7671 Insulation Overcurrent protective eq RCD AFDD Circuit impedances (Ohms) RCD resistance devices Maximum measu earth fault loop impedance Zs Reference Method All circuits Disconnection time Max disconned permitted by E Ring final circuits only Z<sub>S</sub> by voltage Operating current, I∆n (one column to number Test button operation Type of wiring Number of points served Earth Test button operation (measured end to end) Circuit designation Maximum 2 permitted t Live be completed) Capacity Type No Polarity Live срс BS(EN) Rating . Test Circuit Live Live $R_1 + R_2$ $R_2$ r<sub>1</sub> rn r2 mm<sup>2</sup> mm<sup>2</sup> s А kΑ Ω MΩ MΩ V r Ω r r mΑ (Line) (Neutral) (cpc) ms Main Switch N/A 1 Socket А С 1 2.5 1.5 0.4 60898 В 16 10 N/A 2.18 N/A N/A N/A 0.22 N/A LIM >200 500 ~ 0.32 N/A N/A N/A Lights А С 5 1.5 1.0 5 60898 В 10 N/A 5.82 N/A N/A N/A 0.65 N/A LIM >200 500 r 0.75 N/A N/A N/A 2 6 С 60898 В N/A 0.48 N/A LIM **Emergency lights** А 1.5 1.0 5 10 N/A 5.82 N/A N/A >200 500 ~ 0.58 N/A N/A N/A 3 4 6 Door entry А С 1.5 1.0 5 60898 В 6 10 N/A 5.82 N/A N/A N/A 0.31 N/A LIM >200 500 ~ 0.41 N/A N/A N/A 4 1 5 Aerial booster А С 1 1.5 1.0 5 60898 В 6 10 N/A 5.82 N/A N/A N/A 0.36 N/A LIM >200 500 ~ 0.46 N/A N/A N/A С 5 N/A CCTV А 3 2.5 1.5 60898 В 10 10 N/A 3.50 N/A N/A N/A 0.38 LIM >200 500 ~ 0.48 N/A N/A N/A 6 0 - Other А В С D F G Н CODES FOR Thermoplastic Thermoplastic Thermoplastic Thermoplastic Thermoplastic Thermosetting Thermoplastic Mineral TYPE OF insulated/sheathed cables in cables in cables in cables in N/A /SWA cables /SWA cables insulated cables cables metallic conduit nonmetallic conduit metallic trunking nonmetallic trunking WIRING

## DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT GUIDANCE FOR RECIPIENTS

(to be appended to the Report)

This Report is an important and valuable document which should be retained for future reference.

 The purpose of this Report is to confirm, so far as reasonably practicable, whether or not the electrical installation is in a satisfactory condition for continued service (see Section 5). The Report should identify any damage, deterioration, defects and/or conditions which may give rise to danger.
 The person ordering the Report should have received the 'original' Report and the inspector should have retained a duplicate.

3. The 'original' Report should be retained in a safe place and be made available to any person inspecting or undertaking work on the electrical installation in the future. If the property is vacated, this Report will provide the new owner/occupier with details of the condition of the electrical installation at the time the Report was issued.

4. Where the installation incorporates a residual current device (RCD) there should be a notice at or near the device stating that it should be tested six-monthly. For safety reasons it is important that this instruction is followed.

5. Section 4 (Extent and Limitations) should identify fully the extent of the installation covered by this Report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the Report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

6. Some operational limitations such as inability to gain access to parts of the installation or an item of equipment may have been encountered during the inspection. The inspector should have noted these in Section 4.

7. For items classified in Section 7 as C1 ('Danger present'), the safety of those using the installation is at risk, and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work immediately.

8. For items classified in Section 7 as C2 ('Potentially dangerous'), the safety of those using the installation may be at risk and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

9. Where it has been stated in Section 7 that an observation requires further investigation (code FI) the inspection has revealed an apparent deficiency which may result in a code C1 or C2, and could not, due to the extent or limitations of the inspection, be fully identified. Such observations should be investigated without delay. A further examination of the installation will be necessary, to determine the nature and extent of the apparent deficiency (see Section 6).
10. For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a

10. For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. The recommended date by which the next inspection is due is stated in Section 6 of the Report under 'Recommendations' and on a label at or near to the consumer unit/ distribution board.